



The Day After “Heritage Protection Initiative”

Site Monitors Project Idlib Province

Progress Report on Mitigation Project 1 for the Protection of the Mosaics at the Ma’arra Museum: Covering and Sandbagging the Mosaics in the Display Galleries and Repairing Bomb Damage



Preparing the remaining mosaics that are on display in the courtyard by covering them with white glue and TYVEK. Sandbagging the mosaics in the galleries and repairing damage caused by a mortar shell. These efforts are part of the continuing efforts to protect the mosaics in the museum of Ma’arrat Al-Nu’man.

Report prepared and submitted March 13, 2016.



Covering the mosaics with TYVEK and white glue



Cleaning the mosaics prior to covering them with white glue





Applying white glue in preparation for laying on the TYVEK





Applying TYVEK



Filling up sand bags used in protecting the displayed mosaics





Laying down sandbags to protect mosaics





Repairing damage caused by a mortar shell





Reported by:

Eng. Abdul Rahman Alyehia (Syrian Heritage Centre)

Site Monitors Project Coordinator

Dr. Amr Al-Azm

